




<b>Project:</b> Christchurch 2011 Earthquake - EQC Ground Investigations			<b>Page:</b> 1 of 2	<b>CPT-OPA-05</b>	
<b>Test Date:</b> 17-May-2011	<b>Location:</b>		<b>Operator:</b>		
<b>Pre-Drill:</b> 1.2m	<b>Assumed GWL:</b> 4.5mBGL		<b>Located By:</b> Survey GPS		
<b>Position:</b> 2482663.9mE 5739523.9mN 4.726mRL	<b>Coord. System:</b> NZMG & MSL		<b>Comments:</b>		
<b>Other Tests:</b>					



<b>Project:</b> Christchurch 2011 Earthquake - EQC Ground Investigations			<b>Page:</b> 2 of 2	<b>CPT-OPA-05</b>	
<b>Test Date:</b> 17-May-2011	<b>Location:</b>		<b>Operator:</b>		
<b>Pre-Drill:</b> 1.2m	<b>Assumed GWL:</b> 4.5mBGL		<b>Located By:</b> Survey GPS		
<b>Position:</b> 2482663.9mE 5739523.9mN 4.726mRL	<b>Coord. System:</b> NZMG & MSL		<b>Comments:</b>		
<b>Other Tests:</b>					

